General Environmental Incident Summary

Incident: 3247 Date/Time Notice: 3/14/2014 1730 DEM Incident No:

Responsible Party: Enduro Operating

Date Incident: 3/14/2014 Time Incident: 1345 Duration: 3 hours

County: Renville Twp: 158 Rng: 81 Sec: 6 Qtr: SW NE

Lat: 48.53284 Long: -101.18730 Method: Calculated

Location Description: Windrel Central Tank Battery. 2 1/2 miles Northeast of Glenburn ND

Submitted By: Bryan Pease Affiliation: Production Supervisor

Address: 9353 County RD 27B

City: Newburg State: ND Zip: 58762

Received By:

Contact Person: Bryan Pease

9353 County Rd 27B Newburg, ND 58762

Distance Nearest Occupied Building: 0.5 Miles Release Contained: Yes

Type of Incident: Tank Leak

Description of Released Contaminant: Emulsion

Volume Spilled: 20.00 barrels Ag Related: No

EPA Extremely Hazardous Substance: Unknown Reported to NRC: Unknown

Cause of Incident:

Tank bottom started leaking.

Risk Evaluation:

N/A

of Fatalities: # of Injuries: Affected Medium: 03 - soil

Potential Environmental Impacts:

N/A

Action Taken or Planned:

Drain tank and suck up emulsion. Finish cleanup in the Morning.

Wastes Disposal Location: Water to the SWD. Solids to the Prairie Waste Disposal.

Agencies Involved:

Friday, March 27, 2015 Page 1 of 2

Updates

Date: 3/23/2014 Status: Reviewed; O&G Lead Staff: Roberts, Kris

Updated Volume:

Notes:

This release occurred on 3/14/14. It appears that this is on an E&P location. Report forwarded to NDIC for oversight.

Friday, March 27, 2015 Page 2 of 2